

SPEC SHEET + MEASUREMENTS



Wink® WorkFlex Scrub Cap. WW3040

Product photo




- 65/35 poly/cotton
- Mechanical stretch
- Back tie closure
- Covered elastic band
- Wink® heat transfer logo at back

CARE INSTRUCTIONS

Machine Wash Cold With Like Colors. Gentle Cycle. Use Only Non-Chlorine Bleach When Needed. Tumble Dry Low. Remove Promptly From Dryer. Cool Iron When Needed.

Sketches



front

back

SPEC SHEET + MEASUREMENTS



Wink® WorkFlex Scrub Cap. WW3040

PRODUCT MEASUREMENTS

OSFA

Width at
Center
Front 4 1/2

Width at
Center
Back 4 1/4

Width at Center Front: Measure from side to side at center front.

Width at Center Back: Measure from top to bottom at center back.

COLORS



Black
PMS
PROCESS
BLACK C



Ceil Blue
PMS 659C



Navy
PMS 654C



Pewter
PMS 432C



Royal
PMS 2145C



Teal Blue
PMS 320C



White



Wine
PMS 222C